If you are using a printed copy of this procedure, and not the on-screen version, then you <u>MUST</u> make sure the dates at the bottom of the printed copy and the on-screen version match.

The on-screen version of the Collider-Accelerator Department Procedure is the Official Version. Hard copies of all signed, official, C-A Operating Procedures are kept on file in the C-A ESHQ Training Office, Bldg. 911A

#### C-A OPERATIONS PROCEDURES MANUAL

### 14.22.1 Operational Control Form for SMD Mechanical Assembly Operations

Text Pages 2 through 4

### **Hand Processed Changes**

		<del></del>	
HPC No.	<u>Date</u>	Page Nos. I	<u>nitials</u>
	Approved:Collide	Signature on File r-Accelerator Department Chairman	Date
	Approved:	Signature on File	Data
	Superco	onducting Magnet Division Head	Date

M. Van Essendelft

# BNL Environmental Management System Operational Controls Form

OPERATIONAL CONTROL
FOR SIGNIFICANT ENVIRONMENTAL ASPECTS:

COMPLETED BY: M. VAN ESSENDELFT

**DATE:** MARCH 15, 2006

**1. Operation:** SMD Mechanical Assembly Operations (AM-525-MAO)

## 2. Activity(ies):

- 1) Atmospheric discharge from solder & epoxy (may use permitted air emission points)
- 2) Waste generation (hazardous and regulated industrial)
- 3) Chemical storage (flammable)
- 4) Water Usage (discharged to NPDES Permitted Site)
- 5) Liquid Discharge (Component Failure)

## 3. Operational Controls (technological, operational, procedural operating criteria):

- 1) SBMS Subject Area: Generating Waste
- 2) Haz Waste 90 Day Area/Weekly Inspection Program
- 3) Haz Waste Satellite Accumulation Areas
- 4) Chemical Management System (CMS)
- 5) Chemicals Stored in Flammable Storage Cabinets
- 6) Laboratory's Title V Facility Air Emission Permit (NYSDEC 1-4722-0032/00155).
- 7) Log books for permitted air emission points/material use records
- 8) SMD OPM 2.12, "Work Control and Planning"
- 9) SMD OPM 8.1.1.28, Section 4.6, SMD OPM 8.1.1.29, Section 4.1, SMD OPM 8.1.1.38, Section 5.7.2.2 (these apply to Bldg. 924 curing presses only), and SMD OPM 8.1.1.33 (902 Curing Oven).
- **10**) Splash shields to prevent oil leaks (Bldg. 924 curing presses only)
- 11) High level indicator on oil reservoirs, automatic shut down of pump
- 12) Tier I program and self-assessments
- 13) Discharge Monitoring Report (DMR) for Sump HN

#### 4. Maintenance Plan(s):

- 1) Air hoods maintained by MMC on an "as needed basis." Cyclone units maintained by Central Shops on a "as needed basis." No processes are performed when hood is OOC. Facility Support verifies airflow through hood on an annual basis.
- 2) Periodic test of high level indicator light on 924 oil reservoir

# BNL Environmental Management System Operational Controls Form

OPERATIONAL CONTROL
FOR SIGNIFICANT ENVIRONMENTAL ASPECTS:
DATE: MARCH 15, 2006

#### 5. Actions to be Taken if Controls Fail:

- 1) Call spill response hotline X2222
- 2) Local Emergency Plan
- 3) 90 Day Area contingency Plan

#### 6. Records:

- Log books for permitted air hoods/material use records
- Tier I Inspection records /Tracking Database
- 90 Day Area Inspections
- Operational Control Form
- Process Assessment Form/Corrective Action Tracking Database
- SPDES Discharge Monitoring Report

**7. Responsibilities:** [(a) to ensure controls are in place; (b) to ensure controls keep working; (c) to take action when controls fail; (d) to create and keep records relative to operational controls]

Name	Responsibility		
Building Manager	<ul> <li>Maintain air emissions log book/material usage information</li> <li>Maintain Satellite Accumulation areas</li> <li>Spill Control</li> <li>Ensure air hoods are operational</li> </ul>		
Central Shop	Cyclone Unit Maintenance		
SMD Tier I Inspection Committee	Tier I documentation		
90 Day Area Manager/ESH Coordinator	Maintain 90 Day Area per Hazardous Waste Subject Area		
ECR	Update Process Assessment Forms		
ECR	Update PAF Corrective Action Tracking Database		
EWMSD	Maintain SPDES DMR monthly		

# BNL Environmental Management System OPERATIONAL CONTROLS FORM

OPERATIONAL CONTROL COMPLETED BY: M. VAN ESSENDELFT

FOR SIGNIFICANT ENVIRONMENTAL ASPECTS: DATE: MARCH 15, 2006

8. Training:

o. Training.				
Name	Training	Date		
90 Day Area Manager/ESH Coordinator	RCRA 90-Day Area Manager (HP-90Day)	See BTMS Database		
Technician Supervisor	Haz. Waste Generator (HP-RCRIGEN3)			
Technician	AM-ENV-FS4			